


3D Five-Axis C02 Laser Cutting System

This system is intended for three-dimensional trimming and hole cutting on suitable molded non-metal components. Assess the complete part, cutting path and fixture together: access to curved surfaces and openings matters as much as nominal working travel. The published reference uses manual teaching and a part-specific program for repeat processing.



CAD configuration illustration with enclosure closed; final machine and fixture are project-specific.

THREE DECISIONS BEFORE YOU SHORTLIST

- | | |
|---|---|
| 01 Start with the full component | Supply the actual material designation, wall thickness and 3D geometry. Identify every trim line or opening, the edge finish and dimensional acceptance criteria before assessing application suitability. |
| 02 Check path and fixture together | Review cutting-head access around the complete path, not just external part dimensions. A dedicated fixture must support and locate the part while allowing loading and the required cutting movements. |
| 03 Plan teaching and repeat work | Consider how parts are positioned, taught and processed repeatedly. Confirm program creation, batch changes, loading time and sample acceptance together with the enclosure and auxiliary-equipment layout. |

Review the five-axis application decisions

OPTION / PLATFORM	WHEN TO SHORTLIST	CONFIRM BEFORE ORDERING
Material and application	Curved molded non-metal parts requiring trimming or openings on different surfaces.	Actual material, thickness, heat/edge requirements and representative sample processing.
Part and cutting envelope	Use complete 3D geometry and cut locations to assess the working space.	Part, fixture and cutting-head access throughout the required path, not only nominal travel.
Fixture and loading	Repeat processing with a dedicated fixture matched to the component.	Part support, locating method, loading access and clearance for the full cutting motion.
Path programming	The published reference creates and repeats paths through manual teaching.	Teaching method, saved-program management, changeovers and responsibilities for application setup.
Enclosure and auxiliaries	Plan an enclosed processing area with the required supporting equipment.	Guarding, extraction, water cooling, access and final auxiliary-equipment footprint.
Acceptance and cycle	Define the required finished component and practical production rhythm.	Edge quality, part tolerances, sample method and full cycle including loading and unloading.

Positioning is not cut-part tolerance

A machine positioning figure does not establish the tolerance of a finished cut. Material response, fixture, path and the process must be evaluated on the component.

Enclosure images describe a configuration

Published CAD views show open and closed enclosure layouts. An open view illustrates internal arrangement; it is not an instruction to operate without the specified protective enclosure.

Prepare a useful application brief

Material and component

Provide the material designation, wall thickness, dimensions and representative parts. Identify coatings or variations that may change the required sample review and cutting result.

3D model and cut locations

Supply the drawing or 3D model with trim lines and openings marked. Include access constraints and surfaces that require cutting-head approach from different directions.

Quality and acceptance

Define required edge finish, dimensional acceptance and sample checks. Keep finished-part tolerances distinct from machine positioning specifications when agreeing the performance test.

Fixture and loading

Describe the locating concept, part support, loading method and fixture changeovers. Review operator access and clearance along the whole cutting path before fixing the fixture design.

Output and programming

State batch size, target complete cycle and change frequency. Confirm manual teaching, program management, application setup and any training included for the selected configuration.

Installation and supply

Provide available space and utility information. Confirm the enclosure, extraction, cooling and auxiliary layout, together with component supply, installation responsibilities and acceptance records.

A PRACTICAL ROUTE TO A CONFIRMED CONFIGURATION

01 Share

Submit the material, 3D model, trim locations and required finished-part acceptance criteria for application review.

02 Assess

Review sample suitability, cutting-head access, workholding and the complete motion path as one application.

03 Demonstrate

Evaluate a representative component, including taught path, edge quality, dimensions and the full handling cycle.

04 Finalize

Agree the fixture, machine and auxiliary layout, protective configuration and acceptance plan before placing the order.

Published numerical specifications describe a reference configuration and are not repeated here as universal promises. Material suitability, cut-part tolerances, cycle time, fixture and protective arrangement require application review. CAD illustrations show a concept/configuration; they do not establish certification or the final delivered equipment.

OFFICIAL REFERENCES

1. Advanced precision equipment
2. 3D five-axis C02 system
3. Current download library